


Inspection of your Bühler die-casting machine.

Available for Carat 105-440.



Optimizing your die-casting machine.

Inspection of your Bühler die-casting machine to ensure higher machine uptime.

To fulfill productivity expectations, die-casting systems must work smoothly. Usage is associated with wear. Early detection of potential sources of trouble and their elimination are crucial aspects for ensuring high system uptime.

The inspections performed by Bühler take this requirement into account. With its extensive program of condition and performance checks of the mechanical, hydraulic and electric systems of your die-casting machine plus detailed safety checks of personal protection devices, you can keep operating costs low and optimize the utilization of your system.

Benefits for your foundry

- **Enhanced operating reliability** — prevent wear and sources of errors with our inspection
- **Assurance of casting quality** — through checking and adjustment of the machine parameters
- **Increase in efficiency** — plan maintenance through systematic logging of the machine's history
- **Increased Profitability** — Substantial cost reductions through higher machine uptime

Inspection of your Bühler die-casting machine.

Carat 105-440.

	3000h Inspection	6000h Inspection
Inspection		
Checking scraper rings, grease nipple, proximity switches and the central lubrication system		✓
Checking and greasing the split nuts and tie bar grooves		✓
Checking the die		✓
Checking the clamping cylinder for tightness		✓
Checking the drive unit		✓
Checking the machine base		✓
Checking the scrapers on the slide shoes and the height of the slide shoes		✓
Checking the electrical installation wiring		✓
Checking and greasing the tie bar thread	✓	✓
Checking the ejector	✓	✓
Checking the die closing cylinder for tightness	✓	✓
Checking the injection unit	✓	✓
Checking the heat exchanger	✓	✓
Checking the horizontal fastening elements	✓	✓
Checking the hydraulic hoses	✓	✓
Checking the protective devices	✓	✓
Checking the parts at the operator station and replacing the filter mat at the operator device	✓	✓
Checking the filter mat and the condensation drain at the cooling device	✓	✓
Checking the tank ventilation filters	✓	✓
	3000h Inspection	6000h Inspection
Scope of services		
Minimal downtime of the machine during inspection (in work hours); dependent upon on-site conditions	12	24
Written report on the condition of the machine and a list of actions	✓	✓

The inspection is performed by a Bühler service engineer.

For die-casting machines with locking forces in excess of 18'000 kN, two service engineers are needed.

The machine must be in a condition ready for casting.

Bühler AG

Customer Service Die Casting
T +41 71 955 34 45
F +41 71 955 66 55

CH-9240 Uzwil, Switzerland
dc.support@buhlergroup.com
www.buhlergroup.com/die-casting

